## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 763 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

4 2	SECRET/CONT	618	25X1			
COUNTRY	East Germany		REPORT			
SUBJECT	Vietmannsdorf Airfield		DATE DISTR.		22 April 19	54
			NO. OF PAGES	2		
DATE OF INFO.			REQUIREMENT NO.	RD		
PLACE ACQUIRED			REFERENCES			25X1
. T	his is UNEVALUATED Informa	ation	4			
		NS IN THIS REPORT A OF CONTENT IS TENT KEY SEE REVERSE)				25X1
	THE APPRAISAL	OF CONTENT IS TENT				25X

## 1. Runway

- a. During the recent heavy frosts, several cracks have appeared in the main runway. Work has been undertaken to remove the damaged concrete and at three points on the runway, a section 7.4 m in width and approximately 2 m long, has been cut out of the concrete to a depth of the entire thickness of 40 cm.
- b. i) Adjoining the entire length of each side of the main runway, there is an underground water-pipe line situated approximately 1 m from the edge of the concrete and buried 1 m beneath the surface. Above each of these pipe-lines are a series of surface hydrants spaced approximately 50 m apart. During the winter months, these hydrants have been protected from the frost by a wooden box, about 1 m square, packed tightly with straw.
  - 1i) These underground water pipe-lines are connected to a 22 m deep well, which is situated together with a small pump house south of the runway adjoining the former Gross Dölln Vietmannsdorf road.
  - iii) There is no connection between the underground water pipe-lines, which have been permanently embedded in the ground, and the series of temporary surface pipe-lines which have been utilized in mixing the concrete during the recent constructions. Water for this was drawn by means of another temporary pipe-line run from the nearby Gross Gollinsee, and work is now in progress on the clearance and removal of the temporary water system concentrated along the runway and associated taxitracks.

SECRET/CONTROL U.S. OFFICIALS ONLY

STATE X	ARMY	x	NAVY	x	AIR	x	FB1	AEC			

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

	SECRET/	CONTROL	U.S.	OFFICIALS	ONLY
--	---------	---------	------	-----------	------

....

25X

## 2. Security

- a. There appears to have been a distinct tightening up of security arrangements on this project, Russian patrols being obviously more vigilant and the checking of workers' special passes taking place more frequently than in the past.
- b. The Russian detachment of about 100 EM, all wearing black/red shoulder-boards without insignia, has remained unchanged during the period. These troops undertake all guard duties on the airfield.

SECRET/CONTROL U.S. OFFICIALS ONLY